



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 24, 2013

Reviewed: ABB

Mine Name: Black Sands 472288	Permit Number: S/047/0086
Operator Name: Black Sands Holding Co.	Inspection Date: 06/18/2013
Inspector(s): Tom Nicolaysen (intern)	Time: 3:00 PM
Other Participants:	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Permit Fees: Paid 01/20/2013

Bond Amount: \$18,600

Purpose of Inspection:

Inspection of reclamation for bond release

Inspection Summary:

No drill holes were found. There was re-vegetation at the drill site. Roads were sufficiently reclaimed. Some materials were found near the site which may not be related to drilling.

Conclusions and Recommendations:

The site should be released from bond.

Inspector's Signature Tom Nicolaysen

cc: Operator

O:\M047-Uintah\S0470086-BlackSands47288\inspections\ins06182013-86





First drill site to the south east. Re-vegetation and no substantial surface disturbance. UTM NAD 83: E 614382.56, N 4475009.82



Basin and PVC pipe in the ground with a berm around it near the drill site. This may be post mining disturbance.



Another burned area to the north west of the first site with some PVC laying on top. There are some capped wells, one uncapped which is only approx. 4 feet deep.



An access road between the two burned areas. This may be post mining activity.